



VEHICLE INSPECTION REPORT

WJ20HUO

Nissan Juke 1.0 DiG-T Tekna+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	05/03/2020	Body Style	Hatchback	Last service miles	38,711
Year	2020	Keys	2	MOT Due	17/07/2026
Mileage	44,306 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	6	Doors	5
VIN	SJNFAAF16U1030821	Last service date	10/07/2025		

Last Service - 10.7.2025 at 38711 miles (6 main dealer services) Service due

Tyres

NSF	DAVANTI	Worn
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	Damaged
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Tyre of
Damaged
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
Up To 25mm Thru Paint



10: Qtr Panel nsr
Dented
2 Or Less Up To 10mm



11: Wheel osr
Scratched
Up To 50mm



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Over 30mm



14: Roof
Dented
Over 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK