



VEHICLE INSPECTION REPORT

LC700VY

Ford Ranger Pick Up Double Cab Limited 1 2.0 EcoBlue 170

Cat: N **Serious Damage**
 Inspection

Serious Damage? Yes

Vehicle

VAT	Plus VAT
V5	Present



Details

Reg. date	18/12/2020	Body Style	Pick-up	Last service miles	79,903
Year	2020	Keys	1	MOT Due	15/10/2026
Mileage	98,361 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6		
VIN	6FPPXXMJ2PLK12586	Last service date	25/02/2025		

Category N Insurance Loss
 Last Service - 25.02.2025 at 79903 miles (6 services)
 Airbags blown accident damage
 DPF warning light is on

Tyres

NSF	BFGOODRICH	9.0mm
NSR	GOODYEAR	9.0mm
OSF	BFGOODRICH	9.0mm
OSR	BFGOODRICH	9.0mm





Spare

Features


- Bluetooth connection
- Park assist camera
- Front electric windows
- Passenger airbag
- Cruise control
- Rear parking sensor
- Rear electric windows
- Central locking
- Front parking sensor
- Digital radio
- Metallic Paint
- Leather seat trim
- Heated front seat
- Air conditioning
- Drivers airbag

Photos





Condition Check




Damage Photos




1: Bonnet
Dented
With Paint Damage




2: Bumper Front Grill
Broken
Replace




3: Bumper Front
Cracked
Over 25mm




4: Fogdriving Lamp osf
Broken
Replace




5: Bumper Front Moulding
Broken
Replace




6: Wing osf
Chipped
1 To 5




7: Wheel nsf
Scratched
Over 50mm




8: Door nsf
Chipped
Edge Chip




9: Door nsr
Chipped
1 To 5




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




11: Tailgate
Scratched
Over 25mm Thru Paint




12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




13: Door osf
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel of
Scratched
Up To 50mm



16: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK