



VEHICLE INSPECTION REPORT

LG62RVK

Jaguar XF 2.2d [163] Luxury 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	28/12/2012	Body Style	Saloon	Last service miles	45,548
Year	2012	Keys	2	MOT Due	22/01/2027
Mileage	52,887 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	8
Colour	BLACK	Number of stamps	9	Doors	4
VIN	SAJAC05T6DDS65276	Last service date	23/12/2021		

Last service 23/12/2021 at 45548 miles (9 main dealer services). Service required

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Central locking
- Navigation system
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Chipped
1 To 5




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Screen Front
Chipped
Up To 10mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Over 30mm



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
UpTo 25mm Thru Paint




10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Dented
With Paint Damage



13: Boot Lid
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Chipped
1 To 5



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Dented
Over 30mm



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK