

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Toyota Yaris 1.33 VVT-i Icon+ 5dr

| Inspection | | Vehicle | | | nama |
|-----------------|---------------------------|--------------------|--------------|-------------|------------|
| Serious Damage? | No | VAT | Margin | | ₩ 3 |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 20/03/2014 | Keys | 2 | CAP Clean | £4,250.00 |
| Year | 2014 | Service history | Yes | CAP Average | £3,700.00 |
| Mileage | 59,933 Miles Warranted | Service documents | Service Book | CAP Below | £3,100.00 |
| | | Number of stamps | 9 | Gearbox | MANUAL |
| Fuel Type | Petrol | Last service date | 14/05/2025 | Gears | 6 |
| Colour | BLACK | Last service miles | 59,932 | Doors | 5 |
| VIN | VNKKJ3D370A208809 | MOT Due | 14/05/2026 | | - |
| Body Style | Hatchback | | | | |

Last Service - 14.05.2025 at 59932 miles (9 services 8 main dealer)

| Tyres | | | |
|-------|-----------|-------|--|
| NSF | AUTOGREEN | 3.0mm | |
| NSR | BUDGET | 4.0mm | |
| OSF | AUTOGREEN | 4.0mm | |
| OSR | RAPID | 4.0mm | |
| Spare | | | |

Features

- Bluetooth connection
- Rear parking sensor
 Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
 Remote central locking
- Cruise control
- ٠ ٠

٠

- •
- Rear wiper Electric door mirrors Front head restraints Solid Paint ٠
- Isofix child seat anchor points ٠
- · Cloth seat trim
- · Park assist camera Audio remote control
- •
- Air conditioning Height adjustable drivers seat 3x3 point rear seat belts •
- ٠
- Passenger airbag
 Alloy wheels

- PAS

- PAS
 Digital radio
 Climate control
 Rear electric windows
- ABS

- Central locking

Photos




















Eastbourne Car Auctions

Condition Check



Damage Photos






1: Bonnet Chipped 1 To 5

2: Bumper Front Scratched 25 to 100mm Thru Paint





3: Wheel nsf Scratched Up To 50mm



5: Door nsf Chipped Multiple Chips



6: Door nsr Chipped 1 To 5

Dented



7: Wheel nsr Scratched Up To 50mm



8: Bumper Rear Chipped Multiple Chips





9: Wheel osr Scratched Over 50mm



11: Door osr Dented Over 2 UpTo 10mm



13: Wing osf Chipped 1 To 5

 1 To 5



14: Wheel osf Scratched Over 50mm

Dented

With Paint Damage

Interior

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
|--------------------------|----|---|----|
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running | |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |