

VEHICLE INSPECTION REPORT

GY22MLJ

Peugeot 2008 1.2 PureTech Allure Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/04/2022	Colour	ORANGE	MOT Due	29/04/2026
Year	2022	VIN	VR3USHNKKNJ594113	Gearbox	MANUAL
Mileage	TBC	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

Service overdue message displayed

Tyres


NSF	FALKEN	4.0mm
NSR	CONTINENTAL	Worn
OSF	CONTINENTAL	Damaged
OSR	FALKEN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips



8: Door nsr
Dented
With Paint Damage



9: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



10: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint




11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



14: Qtr Panel osr
Chipped
1 To 5



15: Door osr
Scratched
Over 25mm Thru Paint




16: Door osf
Dented
Over 30mm



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Cracked
Replace



20: Tyre osf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition -

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK