



VEHICLE INSPECTION REPORT

EG15OSM

Nissan X-Trail 1.6 dCi N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	18/06/2015	Body Style	Estate	Last service miles	123,612
Year	2015	Keys	2	MOT Due	10/03/2027
Mileage	123,416 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8		
VIN	JN1TCAT32U0014505	Last service date	11/03/2025		

£90 ADDITIONAL FEE.

No V5.

Last service 11/03/2025 at 123162 miles (8 services). Book & print. EML light on car has been plugged in and detects glow plug heater circuit A

And mass or volume air flow circuit A range/performance

Reverse camera faulty

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Chipped
Over 5mm



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Dented
With Paint Damage



10: Wheel osf
Scratched
Over 50mm



11: Door osf
Dented
With Paint Damage



12: Door osf
Dented
Over 30mm



13: Wing osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm



15: Roof
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		