



VEHICLE INSPECTION REPORT

FY10SVU

Volkswagen Touran 1.9 TDI Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/03/2010	Body Style	MPV	Last service miles	136,747
Year	2010	Keys	1	MOT Due	05/02/2027
Mileage	137,699 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	14		
VIN	WVGZZZ1TZAW070936	Last service date	27/01/2026		

£90 ADDITIONAL FEE

Last service 27/01/2026 at 136,747 miles- 14 services (4 main dealer) Book and print
 Mileage of service in 21/01/2021 not recorded
 Cambelt replaced 26/01/2021 at 96,880 miles Noisy engine shaking while idle
 Sat nav SD card missing

Tyres

NSF	FALKEN	4.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	5.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Seat Belt osr
Broken
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: A Post ns
Chipped
1 To 5



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Scratched
Rusted



11: Qtr Panel nsr
Dented
With Paint Damage



12: Sill ns
Rusted
Over 5mm



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Dented
With Paint Damage



15: Tailgate
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Between 10mm + 30mm



19: Sill os
Dented
With Paint Damage



20: Door osr
Scratched
Over 25mm Thru Paint




21: Door osf
Scratched
Over 25mm Thru Paint




22: Wing osf
Dented
With Paint Damage



23: Wheel osf
Scratched
Over 50mm



24: Roof
Chipped
Edge Chip



25: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK