



VEHICLE INSPECTION REPORT

OW23CEU

Polestar 2 170kW 78kWh Long Range Single motor 5dr Auto

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/06/2023	Body Style	Saloon	Last service miles	59,489
Year	2023	Keys	1	MOT Due	13/01/2027
Mileage	86,799 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	WHITE	Number of stamps	3	Doors	4
VIN	YSMVSEGE7PL168598	Last service date	18/12/2024		

EX-TAXI

Last service 18/12/2024 at 59,489 miles- 3 services. Print
 Security watch removed 48 hours after point of sale Type 2 and 3 pin charging cables

Tyres





NSF	MICHELIN	6.0mm
NSR	HANKOOK	6.0mm
OSF	MICHELIN	6.0mm
OSR	HANKOOK	6.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- Park assist camera
- Digital radio
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Body coloured bumpers
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking


Photos









Condition Check




Damage Photos




1: Bumper Front
Scratched
25 to 100mm Thru Paint




2: Wheel nsf
Scratched
Over 50mm




3: Door nsf
Chipped
Edge Chip




4: Wheel nsr
Scratched
Over 50mm




5: Bumper Rear
Scratched
25 to 100mm Thru Paint




6: Boot Lid
Poor Previous Repair
Poor Colour




7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Chipped
Edge Chip



9: Door osr
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK