



VEHICLE INSPECTION REPORT

GN15YOM

Mazda MX-5 1.8i Sport Venture Edition 2dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/04/2015	VIN	JMZNCA88200362366	Last service date	14/08/2025
Year	2015	Body Style	Convertible	Last service miles	136,942
Mileage	144,826 Miles Warranted	Keys	2	MOT Due	13/08/2026
Fuel Type	Petrol	Service history	Yes	Gearbox	MANUAL
Colour	BLUE	Number of stamps	3	Gears	5

£90 ADDITIONAL FEE

Last service 14/08/2025 at 136,942 miles- 3 main dealer services confirmed by Hendy, Tunbridge Wells Traction control warning light is on

Tyres


NSF	BRIDGESTONE	3.0mm
NSR	CONTINENTAL	3.0mm
OSF	BRIDGESTONE	4.0mm
OSR	TRIANGLE	6.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Body coloured bumpers
- Climate control
- Drivers airbag
- Central locking
- Navigation system
- Electric door mirrors
- Front electric windows
- Passenger airbag
- Remote central locking
- Telephone
- Electric sunroof
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check




Damage Photos




1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Dented
Over 30mm




3: Bumper Front
Chipped
Multiple Chips




4: Front TowEye Cvr
Missing
Replace




5: Wheel nsf
Scratched
Over 50mm




6: Wing nsf
Poor Previous Repair
Poor Paint




7: Screen Front
Scratched
Over 30mm




8: Door nsf
Poor Previous Repair
Rippled UpTo 30%




9: Wheel nsr
Scratched
Up To 50mm




10: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%




11: Boot Lid
Scratched
Over 25mm Thru Paint




12: Bumper Rear
Scratched
25 to 100mm Thru Paint




13: Qtr Panel osr
Scratched
Over 25mm Thru Paint




14: Wheel osr
Scratched
Over 50mm




15: Door osf
Chipped
Multiple Chips




16: Door osf
Dented
Between 10mm + 30mm




17: Wing osf
Dented
Between 10mm + 30mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Roof
Chipped
Multiple Chips

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		