



VEHICLE INSPECTION REPORT

VK58BUP

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	30/09/2008	Keys	2	CAP Clean	£1,150.00
Year	2008	Service history	Yes	CAP Average	£750.00
Mileage	158,233 Miles Warranted	Service documents	Service Book	CAP Below	£400.00
Fuel Type	Diesel	Number of stamps	14	Gearbox	MANUAL
Colour	SILVER	Last service date	20/10/2021	Gears	6
VIN	WVWZZZ1KZ9W054537	Last service miles	139,964	Doors	5
Body Style	Hatchback	MOT Due	10/10/2025		

Last Service - 20.10.2021 at 139964 miles (14 services)

Roof lining sagged

Bonnet doesn't shut

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Heated front seat
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Leather seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Rusted
Over 5mm



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Door nsf
Rusted
UpTo 5mm



11: Sill ns
Rusted
UpTo 5mm



12: Wing nsf
Rusted
Over 5mm



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bumper Front
Chipped
Multiple Chips



16: Bonnet
Poor Previous Repair
Poor Paint



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK