



# VEHICLE INSPECTION REPORT

**SP63SGZ**

## Ford C-Max 1.0 EcoBoost 125 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	03/10/2013	Body Style	MPV	Last service miles	71,901
Year	2013	Keys	2	MOT Due	01/02/2027
Mileage	80,628 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BROWN	Number of stamps	5		
VIN	WF0JXXWPBJDG16716	Last service date	27/01/2025		

Last service 27/01/2025 at 71,901 miles- 5 services (4 main dealer) Book

### Tyres


NSF	TRIANGLE	5.0mm
NSR	MAZZINI	5.0mm
OSF	TRIANGLE	5.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos




1: Bonnet  
Dented  
Between 10mm + 30mm



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



6: Screen Front  
Chipped  
Over 10mm



7: Door nsf  
Chipped  
1 To 5



8: Door nsf  
Chipped  
Edge Chip



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Dented  
With Paint Damage



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Tailgate  
Scratched  
Over 25mm Thru Paint



14: Lamp osr  
Broken  
Replace



15: Qtr Panel osr  
Dented  
With Paint Damage



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Scratched  
Over 25mm Thru Paint



18: Door osf  
Chipped  
Edge Chip



19: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



20: Wheel osf  
Scratched  
Over 50mm



21: A Post os  
Dented  
Over 30mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK