



VEHICLE INSPECTION REPORT

YK58MUY

Vauxhall Astra 1.6i 16V Club [115] 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 01/09/2008

Year 2008

Mileage 136,669 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN W0LOAHL4888113172

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Last service date 07/05/2025

Last service miles 134,921

MOT Due 30/06/2025

CAP Clean £400.00

CAP Average £200.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

Doors 5

£65 ADDITIONAL FEE Last service 07/05/2025 @ 134921 miles (3 SERVICES) exhaust blowing

Tyres

NSF BUDGET 3.0mm

NSR BUDGET 3.0mm

OSF AUTOGRIP 2.0mm

OSR BUDGET 3.0mm


Spare

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Grill
Broken
Replace




4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Rusted
Over 5mm



7: Door nsr
Scratched
Over 25mm Not Thru Paint




8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Other
N/A
N/A



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK