



VEHICLE INSPECTION REPORT

LM13BHJ

Kia Picanto 1.0 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/04/2013	Body Style	Hatchback	Last service miles	71,229
Year	2013	Keys	1	MOT Due	06/12/2026
Mileage	94,625 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	7	Doors	5
VIN	KNABE511LDT507649	Last service date	09/03/2020		

£100 ADDITIONAL FEE.

last service 9/3/20 @ 71,229 miles (7 services 6 main dealer) book & print Eml light is on
 Car been plugged in and detected;
 Cylinder 2 misfire
 Catalyst system faulty
 Random cylinder misfire
 Smells of petrol possible leak
 Rubbing noise from rear suspension

Tyres

NSF	INFINITY	4.0mm
NSR	EVENT	Damaged
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Rear wiper
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Radio/CD
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Body coloured bumpers
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Seat Base Cover osf
Scuffed
Over 25mm



3: Seat Base Cover nsr
Soiled
Light



4: Tyre nsr
Damaged
Replace



5: Bonnet
Chipped
1 To 5



6: Bumper Front
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
With Paint Damage



9: Sill ns
Dented
With Paint Damage



10: Qtr Panel nsr
Dented
With Paint Damage



11: B Post ns
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: B Post os
Dented
Between 10mm + 30mm



14: Bumper Rear
Insecure
Action Required



15: Sill os
Dented
With Paint Damage



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Dented
Between 10mm + 30mm



19: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK