



VEHICLE INSPECTION REPORT

LG68HJZ

Kia Sportage 1.6T GDi GT-Line S 5dr DCT Auto [AWD]

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	27/09/2018	Body Style	Estate	Last service miles	58,815
Year	2018	Keys	2	MOT Due	Expired
Mileage	70,072 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	BLACK	Number of stamps	4		
VIN	U5YPK816WJL540382	Last service date	03/01/2025		

£100 ADDITIONAL FEE.

Last service 03/01/2025 at 58,815 miles- 4 main dealer services. Book
 MOT EXPIRED Engine tappy
 Service light on

Tyres


NSF	BUDGET	6.0mm
NSR	TRIANGLE	5.0mm
OSF	BUDGET	6.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check




Damage Photos




1: Wheel of
Scratched
Over 50mm




2: Wing of
Chipped
1 To 5




3: Door osr
Chipped
1 To 5




4: Door osr
Chipped
Edge Chip




5: Bumper Rear
Scratched
Over 25mm Not Thru Paint




6: Door nsf
Scratched
Over 25mm Thru Paint




7: Wing nsf
Scratched
Over 25mm Not Thru Paint




8: Wheel nsf
Scratched
Over 50mm




9: Door osr
Scratched
Over 25mm Not Thru Paint



10: Door osf
Chipped
Multiple Chips



11: Door nsr
Chipped
Multiple Chips



12: Front TowEye Cvr
Missing
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK