



VEHICLE INSPECTION REPORT

CA69GBF

Peugeot 5008 1.2 PureTech GT Line Premium 5dr EAT8

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	18/12/2019	Body Style	MPV	Last service miles	44,226
Year	2019	Keys	2	MOT Due	Expired
Mileage	48,375 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	8
Colour	GREY	Number of stamps	6		
VIN	VF3MRHNSUKS469948	Last service date	03/07/2025		

£100 ADDITIONAL FEE.

Last service 03/07/2025 at 44226 miles (6 services (4 main dealer). Book & print.
MOT EXPIRED

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	MICHELIN	2.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check




Damage Photos




1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm




4: Door nsf
Dented
Between 10mm + 30mm




5: Door nsf
Chipped
Multiple Chips




6: Door nsr
Scratched
Over 25mm Thru Paint




7: Wheel nsr
Scratched
Over 50mm




8: Qtr Panel nsr
Chipped
1 To 5




9: Wheel osr
Scratched
Over 50mm




10: Door osr
Scratched
Over 25mm Thru Paint




11: Door osf
Dented
With Paint Damage



12: Wheel osf
Scratched
Over 50mm



13: Seat Base Cover osf
Scuffed
Over 25mm



14: Door nsr
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		