



VEHICLE INSPECTION REPORT

DU69OLR

Vauxhall Astra 1.6 CDTi 16V ecoTEC Tech Line Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2019	Body Style	Estate	Last service miles	75,593
Year	2019	Keys	2	MOT Due	27/01/2027
Mileage	81,678 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8		
VIN	W0VBD8EN0K8008612	Last service date	15/12/2025		

Last Service - 15.12.2025 at 75593 miles (8 services)
EX TAXI Engine noisy tapping

Tyres

NSF	BUDGET	5.0mm
NSR	FULDA	5.0mm
OSF	BUDGET	5.0mm
OSR	FULDA	5.0mm
Spare		Worn

Features


- Bluetooth connection
- PAS
- Digital radio
- Full size spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Rippled Up To 30%



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Poor Previous Repair
Poor Paint



6: Door nsf
Poor Previous Repair
Rippled UpTo 30%



7: Door nsr
Poor Previous Repair
Rippled UpTo 30%



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Poor Previous Repair
Rippled UpTo 30%



12: Aerial
Missing
Replace



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osr
Dented
Over 2 UpTo 10mm



16: Door osf
Scratched
Over 25mm Thru Paint




17: Wing osf
Poor Previous Repair
Poor Paint



18: Wheel osf
Scratched
Up To 50mm



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Scratched
Over 25mm Not Thru Paint



21: Bumper Front Moulding
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK