



VEHICLE INSPECTION REPORT

DH60SEP

Renault Laguna 1.5 dCi eco2 Dynamique TomTom 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2010	Colour	GREY	Service history	None
Year	2010	VIN	VF1KT0A0643857203	MOT Due	24/10/2026
Mileage	96,887 Miles Warranted	Body Style	Estate	Gearbox	MANUAL
Fuel Type	Diesel	Keys	2	Gears	6

£90 ADDITIONAL FEE

NO SERVICE HISTORY Boot will not stay open

Tyres

NSF	ACCELERA	5.0mm
NSR	BUDGET	5.0mm
OSF	ACCELERA	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osr
Soiled
Light



2: Carpets Front
Holed
Over 3mm



3: Seat Base Cover osf
Scuffed
Over 25mm



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Bumper Front Moulding
Missing
Replace



7: Wheel nsf
Scratched
Over 50mm



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Wing nsf
Rusted
Over 5mm



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Other
N/A
N/A



15: Bumper Rear
Dented
With Paint Damage



16: Tailgate
Scratched
Over 25mm Thru Paint



17: B Post ns
Dented
Between 10mm + 30mm



18: B Post os
Dented
With Paint Damage



19: Fuel Flap
Missing
Replace



20: Wheel osr
Scratched
Over 50mm



21: Qtr Panel osf
Scratched
Over 25mm Thru Paint



22: Door osf
Chipped
1 To 5




23: Door osf
Dented
Between 10mm + 30mm



24: Wing osf
Scratched
Over 25mm Thru Paint



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Chipped
UpTo 10mm



27: Roof
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK