



VEHICLE INSPECTION REPORT

FX61DHC

Lexus RX 450h 3.5 SE-L 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	26/09/2011	Keys	3	CAP Clean	£5,150.00
Year	2011	Service history	Yes	CAP Average	£4,475.00
Mileage	132,572 Miles Warranted	Service documents	Service Book	CAP Below	£3,800.00
Fuel Type	Hybrid Electric	Number of stamps	6	Gearbox	CVT
Colour	BLACK	Last service date	09/05/2025	Gears	1
VIN	JTJBC11A902424078	Last service miles	132,511		
Body Style	Estate	MOT Due	18/08/2025		

Last service 09/05/2025 @ 132511 miles (6 SERVICES 4 MAIN DEALER)

Tyres


NSF	BUDGET	4.0mm
NSR	COOPER TIRES	5.0mm
OSF	ZEETEX	4.0mm
OSR	COOPER TIRES	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Door osr
Dented
Between 10mm + 30mm



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Chipped
1 To 5



12: Door nsr
Scratched
Over 25mm Not Thru Paint



13: Door nsf
Poor Previous Repair
Poor Paint



14: Wing nsf
Poor Previous Repair
Poor Paint



15: Bumper Front
Scratched
25 to 100mm Thru Paint

16:



17: Bonnet
Scratched
Over 25mm Thru Paint

18: Bumper Rear
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK