



# VEHICLE INSPECTION REPORT

**RY19BUO**

## Kia Sportage 1.6T GDi ISG 4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	27/06/2019	Body Style	Estate	Last service miles	18,730
Year	2019	Keys	1	MOT Due	Expired
Mileage	46,518 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	1		
VIN	U5YPH816LKL652794	Last service date	30/04/2022		

### £90 ADDITIONAL FEE

Last service 30/04/2022 at 18,730 miles- 1 service. Book  
MOT EXPIRED Fuel flap not closing properly  
Near side mirror camera faulty

### Tyres



NSF	HANKOOK	2.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	2.0mm
OSR	HANKOOK	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

## Photos





# Condition Check




## Damage Photos




1: Bonnet  
Scratched  
Over 25mm Thru Paint




2: Bumper Front  
Scratched  
25 to 100mm Thru Paint




3: Wheel nsf  
Scratched  
Over 50mm




4: Wing nsf  
Chipped  
1 To 5




5: Door nsf  
Scratched  
Over 25mm Thru Paint




6: Door nsr  
Dented  
With Paint Damage




7: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm




8: Wheel nsr  
Scratched  
Over 50mm




9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint




10: Bumper Front  
Scratched  
25 to 100mm Thru Paint




11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint




12: B Post os  
Dented  
2 Or Less UpTo 10mm




13: Wheel osr  
Scratched  
Over 50mm




14: Door osr  
Dented  
Over 30% Of Panel




15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Wing osf  
Scratched  
UpTo 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: Bumper Front  
Insecure  
Action Required

**Interior**

**Carpet Condition**            Average  
**Seat Condition**            Average

**Upholstery Condition**    Average  
**Odour**                            No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

**Additional fees may apply to some vendors.**  
**Please note buyers rate increase from 01/01/2025**

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		