

VEHICLE INSPECTION REPORT

AP22JFZ

Ford Focus 1.5 EcoBlue ST-Line 5dr Auto

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

nama
GRADE
2

Details

| | | | | | |
|-----------|------------------------|--------------------|------------|---------|------------|
| Reg. date | 22/07/2022 | Body Style | Hatchback | MOT Due | 14/01/2027 |
| Year | 2022 | Keys | 2 | Gearbox | AUTOMATIC |
| Mileage | 22,920 Miles Warranted | Service history | Yes | Gears | 8 |
| Fuel Type | Diesel | Number of stamps | 1 | Doors | 5 |
| Colour | BLACK | Last service date | 20/01/2024 | | |
| VIN | WF0NXXGCHNNT50205 | Last service miles | 10,833 | | |

Last service 20/01/2024 at 10,833 miles- 1 main dealer service confirmed by Busseys Ford, Norwich

Tyres


| | | |
|-------|-------------|-------|
| NSF | CONTINENTAL | 3.0mm |
| NSR | CONTINENTAL | 5.0mm |
| OSF | CONTINENTAL | 4.0mm |
| OSR | CONTINENTAL | 5.0mm |
| Spare | | |

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos




1: Wheel of
Scratched
Over 50mm




2: Wing of
Chipped
1 To 5




3: Door osf
Scratched
Up To 25mm Not Thru Paint




4: Other
N/A
N/A




5: Bumper Rear
Scratched
Up To 25mm Thru Paint




6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




7: Door nsr
Scratched
Over 25mm Not Thru Paint




8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Chipped
Multiple Chips



10: Bonnet
Chipped
1 To 5



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |