



# VEHICLE INSPECTION REPORT

**LF72TYD**

## Volkswagen Polo 1.0 TSI Life 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	14/09/2022	Body Style	Hatchback	Last service miles	7,400
Year	2022	Keys	2	MOT Due	13/09/2026
Mileage	9,532 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	2	Doors	5
VIN	WVVZZZAWZNU078027	Last service date	22/08/2025		

£100 ADDITIONAL FEE

Last service 22/08/2025 at 7400 miles- 2 main dealer services. Print

### Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check




## Damage Photos




1: Bumper Rear  
Scratched  
Over 100mm Thru Paint




2: Boot Lid  
Dented  
Over 2 UpTo 10mm




3: Qtr Panel osr  
Dented  
With Paint Damage




4: Wheel osr  
Scratched  
Up To 50mm




5: Door osr  
Poor Previous Repair  
Poor Paint




6: Door osf  
Poor Previous Repair  
Poor Paint




7: Wing of  
Scratched  
Over 25mm Thru Paint




8: Bonnet  
Chipped  
1 To 5




9: Wheel of  
Scratched  
Up To 50mm




10: Bumper Front  
Scratched  
Over 100mm Thru Paint




11: Wing nsf  
Dented  
With Paint Damage




12: Wheel nsf  
Scratched  
Over 50mm




13: Door nsf  
Dented  
With Paint Damage



14: Door nsr  
Dented  
With Paint Damage



15: Qtr Panel nsr  
Dented  
With Paint Damage



16: Wheel nsr  
Scratched  
Over 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK