



# VEHICLE INSPECTION REPORT

**EK73YWC**

## Kia Stonic 1.0T GDi 48V GT-Line S 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/09/2023	Body Style	Hatchback	Last service miles	16,632
Year	2023	Keys	2	MOT Due	28/09/2026
Mileage	16,793 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Hybrid Electric	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	1	Doors	5
VIN	KNADD817VRT907177	Last service date	12/09/2025		

£100 ADDITIONAL FEE

Last service 12/09/2025 at 16,632 miles- 1 service. Print No boot floor

### Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	PIRELLI	4.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

### Photos







## Condition Check




## Damage Photos




1: Bonnet  
Poor Previous Repair  
Poor Paint




2: Bumper Front  
Poor Previous Repair  
Poor Paint




3: Wheel nsf  
Scratched  
Up To 50mm




4: Wing nsf  
Scratched  
Over 25mm Thru Paint




5: Door nsf  
Poor Previous Repair  
Poor Paint




6: Door nsr  
Poor Previous Repair  
Poor Paint



7: Qtr Panel nsr  
Dented  
Over 30mm




8: Wheel nsr  
Scratched  
Up To 50mm




9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




11: Boot Lid  
Dented  
Over 30mm




12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




13: Wheel osr  
Scratched  
Up To 50mm




14: Door osr  
Chipped  
Multiple Chips




15: Door osf  
Poor Previous Repair  
Poor Paint



16: Wing osf  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osf  
Corroded  
Light



18: Roof  
Dented  
Between 10mm + 30mm

**Interior**

**Carpet Condition**            Average  
**Seat Condition**            Average

**Upholstery Condition**    Average  
**Odour**                        No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

**Additional fees may apply to some vendors.**  
**Please note buyers rate increase from 01/01/2025**

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK