



# VEHICLE INSPECTION REPORT

**MA10CWK**

## Ford KA 1.2 Zetec 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	23/03/2010	Body Style	Hatchback	Last service miles	75,095
Year	2010	Keys	2	MOT Due	09/02/2027
Mileage	97,321 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	7	Doors	3
VIN	WF0UXXLTRUAY59521	Last service date	13/12/2019		

£90 ADDITIONAL FEE.

last service 13/12/19 @ 75,095 miles ( 7 services 1 main dealer) print Only one key will start the car  
 Noisy engine

### Tyres


NSF	BUDGET	5.0mm
NSR	RAPID	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- PAS
- Electric door mirrors
- Front head restraints
- Solid Paint
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Central locking
- Radio/CD
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
Multiple Chips



2: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



3: Door osf  
Chipped  
1 To 5



4: Door osf  
Chipped  
Edge Chip



5: Qtr Panel osr  
Chipped  
1 To 5



6: Wheel osr  
Scratched  
Up To 50mm



7: Bumper Rear  
Scratched  
Over 100mm Thru Paint



8: Tailgate  
Dented  
Between 10mm + 30mm



9: Wheel nsf  
Scratched  
Up To 50mm



10: Qtr Panel nsf  
Poor Previous Repair  
Poor Paint



11: Door nsf  
Poor Previous Repair  
Poor Paint



12: Wing nsf  
Poor Previous Repair  
Poor Paint



13: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



14: Wheel nsf  
Scratched  
Up To 50mm



15: Bumper Front  
Scratched  
25 to 100mm Thru Paint



16: Bumper Front  
Chipped  
Multiple Chips



17: Bonnet  
Poor Previous Repair  
Paint Flake



18: Screen Front  
Chipped  
Up To 10mm



19: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK