



# VEHICLE INSPECTION REPORT

**GF60WFB**

## Volkswagen Golf 1.6 TDi 105 S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	17/11/2010	VIN	WVWZZZ1KZBP054446	Gearbox	MANUAL
Year	2010	Body Style	Hatchback	Gears	5
Mileage	149,684 Miles Warranted	Keys	1	Doors	5
Fuel Type	Diesel	Service history	None		
Colour	BLACK	MOT Due	28/04/2026		

£65 ADDITIONAL FEE.  
 NO SERVICE HISTORY

### Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	4.0mm
Spare		

## Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage




2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Door Mirror Assy nsf  
Broken  
Replace



5: Fogdriving Lamp nsf  
Broken  
Replace



6: A Post ns  
Dented  
Over 30mm



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Tailgate  
Scratched  
Over 25mm Thru Paint



13: Other  
N/A  
N/A



14: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Scratched  
Rusted



17: Door osf  
Dented  
With Paint Damage



18: Wing osf  
Chipped  
Multiple Chips



19: Wheel osf  
Scratched  
Over 50mm



20: Carpets Front  
Scuffed  
Over 25mm



21: Roof Lining  
Scuffed  
Over 25mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK