



# VEHICLE INSPECTION REPORT

**GY18SKO**

## Kia Sportage 1.7 CRDi ISG 2 5dr

nama  
GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	07/05/2018	Body Style	Estate	Last service miles	139,884
Year	2018	Keys	2	MOT Due	06/05/2026
Mileage	147,880 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	11		
VIN	U5YPH815LJL463694	Last service date	10/12/2025		

Last Service - 10.12.2025 at 139884 miles (11 services) Low clutch

### Tyres


NSF	GT RADIAL	5.0mm
NSR	GT RADIAL	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos







## Condition Check




## Damage Photos




1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Poor Previous Repair  
Poor Paint




3: Wing nsf  
Chipped  
1 To 5




4: Door nsf  
Scratched  
Over 25mm Thru Paint




5: Door nsr  
Chipped  
Edge Chip




6: Qtr Panel nsr  
Chipped  
1 To 5




7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint





8: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



9: Door osr  
Scratched  
UpTo 25mm Thru Paint



10: Door osf  
Dented  
Between 10mm + 30mm



11: Wing of  
Chipped  
1 To 5

12: Bumper Rear  
Poor Previous Repair  
Poor Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK