



VEHICLE INSPECTION REPORT

BU14XEA

BMW X5 xDrive30d M Sport 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	10/03/2014	Body Style	Estate	Last service miles	128,991
Year	2014	Keys	2	MOT Due	06/11/2026
Mileage	129,542 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	11		
VIN	WBAKS420300G63778	Last service date	02/03/2026		

£90 ADDITIONAL FEE. Some services stored in on-board system.

Last Service - 02.03.2026 at 128991 miles (11 services (5 main dealer) Steering rack cover lose . Engine Noisy

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BUDGET	2.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking


Photos









Condition Check




Damage Photos




1: Bonnet
Chipped
1 To 5




2: Bumper Front
Dented
With Paint Damage




3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint




6: Door nsf
Dented
With Paint Damage




7: Door nsr
Poor Previous Repair
Poor Paint




8: Qtr Panel nsr
Poor Previous Repair
Poor Paint




9: Wheel nsr
Scratched
Over 50mm




10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Boot Lid
Dented
Between 10mm + 30mm




12: Boot Lid
Scratched
Over 25mm Not Thru Paint




13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




14: Wheel osr
Scratched
Over 50mm




15: Door osr
Dented
Over 2 UpTo 10mm




16: Door osr
Scratched
Over 25mm Not Thru Paint




17: Door osf
Chipped
Multiple Chips




18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Wheel ofscratched Over 50mm



20: Seat Base Cover of Torn Over 3mm



21: Centre Console Front Scuffed Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		