



VEHICLE INSPECTION REPORT

YK64XLP

Alfa Romeo Giulietta 1.6 JTDM-2 Distinctive 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	15/10/2014	Body Style	Hatchback	Last service miles	91,729
Year	2014	Keys	2	MOT Due	01/11/2026
Mileage	95,101 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	11	Doors	5
VIN	ZAR94000007358821	Last service date	23/10/2025		

£90 ADDITIONAL FEE

Last Service - 23.10.2025 at 91729 miles (11 services)

Car been plugged in and detected
 Park/ neutral switch input circuit

Tyres

NSF	BUDGET	4.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	4.0mm
OSR	NEXEN	5.0mm


Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wheel nsf
Scratched
Over 50mm



4: Wing osf
Dented
Between 10mm + 30mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Chipped
1 To 5



9: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



10: Wheel osr
Corroded
Light



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Poor Previous Repair
Poor Paint



13: Door osf
Rusted
UpTo 5mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
 Scratched
 Over 25mm Thru Paint



16: Fog Lamp Surround os
 Broken
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK