



VEHICLE INSPECTION REPORT

VF66DZM

Peugeot 2008 1.6 BlueHDi 100 Allure 5dr [Start Stop]

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	28/02/2017	VIN	VF3CUBHYKHY030020	Gearbox	MANUAL
Year	2017	Body Style	Hatchback	Gears	5
Mileage	119,378 Miles Warranted	Keys	2	Doors	5
Fuel Type	Diesel	Service history	None		
Colour	RED	MOT Due	03/12/2026		

£90 ADDITIONAL FEE
 NO SERVICE HISTORY Service due message displayed

Tyres



NSF	PIRELLI	2.0mm
NSR	INVOVIC	5.0mm
OSF	PIRELLI	Damaged
OSR	KUMHO	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- PAS
- Digital radio
- Full size spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Flasher Side Repeater ns
Broken
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Tyre osf
Damaged
Replace



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Scratched
Over 25mm Thru Paint




16: Door osf
Scratched
Over 25mm Thru Paint



17: Wing osf
Dented
Between 10mm + 30mm



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Poor Previous Repair
Paint Flake

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK