



# VEHICLE INSPECTION REPORT

**GF12TYZ**

## Skoda Octavia 2.0 TDI CR SE Plus 5dr

nama  
GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	07/06/2012	Body Style	Estate	Last service miles	134,457
Year	2012	Keys	2	MOT Due	12/08/2026
Mileage	139,182 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	6		
VIN	TMBHE21Z6C2085867	Last service date	09/01/2026		

### £90 ADDITIONAL FEE

last service 9/1/26 @ 134,457 miles (6 services 1 main dealer) print  
 replaced clutch and tensioner on 17/1/25 @ 114,929 miles

### Tyres

NSF	BRIDGESTONE	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Heated door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Door Pad osf  
Scuffed  
Over 25mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Chipped  
Over 5mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsr  
Dented  
Over 30mm



8: Wheel nsr  
Scratched  
Over 50mm



9: Sill ns  
Dented  
Over 30mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Tailgate  
Dented  
With Paint Damage



13: Screen Rear  
Scratched  
Over 30mm



14: Roof  
Dented  
Over 30mm



15: Wheel osr  
Scratched  
Over 50mm



16: Qtr Panel osr  
Rusted  
Over 5mm



17: Door osr  
Dented  
With Paint Damage



18: Door osf  
Chipped  
Edge Chip



19: Door Mirror Glass os  
Broken  
Replace



20: Flasher Side Repeater os  
Broken  
Replace



21: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



22: Wheel osf  
Scratched  
Over 50mm



23: Wing osf  
Chipped  
1 To 5



24: Screen Front  
Chipped  
Over 10mm



25: Tyre nsf  
Damaged  
Replace



26: Fascia Trim  
Damaged  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK