



VEHICLE INSPECTION REPORT

BG64HFA

Subaru XV 2.0D SE Premium 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	28/11/2014	Body Style	Hatchback	Last service miles	91,003
Year	2014	Keys	2	MOT Due	25/11/2026
Mileage	93,113 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	JF1GPDKZ3EG146366	Last service date	11/11/2025		

last service 11/11/25 @ 91,003 miles (5 services 2 main dealer) book & print Service due message displayed
 Exhaust blowing
 Engine tapping

Tyres


NSF	GOODYEAR	5.0mm
NSR	MICHELIN	5.0mm
OSF	GOODYEAR	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint




6: Door nsr
Dented
Between 10mm + 30mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Door osr
 Scratched
 UpTo 25mm Thru Paint



10: Door osf
 Dented
 Over 30mm



11: Wing osf
 Chipped
 1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK