



VEHICLE INSPECTION REPORT

FG18BZJ

Toyota Auris 1.8 Hybrid Excel TSS 5dr CVT [Leather]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy



Details

Reg. date	06/04/2018	VIN	SB1MS3JE10E415813	CAP Average	£8,875.00
Year	2018	Body Style	Hatchback	CAP Below	£7,825.00
Mileage	64,109 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Hybrid Electric	MOT Due	01/10/2025	Gears	1
Colour	BLUE	CAP Clean	£9,600.00	Doors	5

£100 ADDITIONAL FEE. Copy V5.

Tyres


NSF	ROADSTONE	4.0mm
NSR	DUNLOP	3.0mm
OSF	ROADSTONE	4.0mm
OSR	DUNLOP	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Telephone
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5




4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5




7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint




10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
1 To 5



15: Wing osf
Chipped
1 To 5



16: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK