



# VEHICLE INSPECTION REPORT

**MA18AZX**

## Volkswagen Golf 1.5 TSI EVO 150 GT 5dr DSG

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	15/03/2018	Body Style	Hatchback	MOT Due	10/01/2027
Year	2018	Keys	1	Gearbox	SEMI AUTO
Mileage	47,847 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	Petrol	Number of stamps	2	Doors	5
Colour	BLACK	Last service date	11/12/2025		
VIN	WVVZZZAUZJW203593	Last service miles	47,209		

£90 ADDITIONAL FEE

Last service 11/12/2025 at 47,209 miles- 2 services confirmed by Miles Garage, Royal Tunbridge Wells

### Tyres

NSF	FALKEN	5.0mm
NSR	BUDGET	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

### Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

### Photos





## Condition Check




## Damage Photos




1: Wheel or  
Scratched  
Over 50mm




2: Wing or  
Dented  
Over 30mm




3: Door osf  
Chipped  
1 To 5




4: Door osf  
Scratched  
Over 25mm Not Thru Paint




5: Qtr Panel osr  
Chipped  
Edge Chip




6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




7: Qtr Panel nsr  
Chipped  
1 To 5




8: Door nsr  
Chipped  
1 To 5




9: Door nsr  
Dented  
2 Or Less UpTo 10mm




10: Wheel nsf  
Scratched  
Over 50mm



11: Wing nsf  
Scratched  
Over 25mm Thru Paint



12: Bumper Front  
Scratched  
Over 100mm Thru Paint



13: Bonnet  
Chipped  
1 To 5

### Interior

**Carpet Condition**            Average  
**Seat Condition**            Average

**Upholstery Condition**    Average  
**Odour**                        No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

**Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025**

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK