



VEHICLE INSPECTION REPORT

LM57KBJ

Volkswagen Golf 1.9 Match TDI 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	18/02/2008	Body Style	Hatchback	Last service miles	198,486
Year	2008	Keys	2	MOT Due	Expired
Mileage	202,691 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	6	Doors	5
VIN	WVWZZZ1KZ8P048353	Last service date	06/01/2025		

£90 ADDITIONAL FEE
 MOT expired
 Last service 06/01/2025 at 198,486 miles- 6 services

Tyres

NSF	BUDGET	4.0mm
NSR	RAPID	4.0mm
OSF	CONSTANCY	3.0mm
OSR	BFGOODRICH	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing of
Poor Previous Repair
Poor Paint



2: Wheel of
Scratched
Over 50mm



3: Door Mirror Assy osf
Broken
Replace



4: Door osf
Dented
With Paint Damage



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Tailgate
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Door nsf
Dented
Over 30mm



12: Door nsr
Scratched
UpTo 25mm Thru Paint



13: Sill ns
Dented
With Paint Damage



14: Wing nsf
Dented
With Paint Damage



15: Wheel nsf
Scratched
Over 50mm



16: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Bumper Front
Scratched
Over 100mm Thru Paint



18: Fog Lamp Surround ns
Missing
Replace



19: Fog Lamp Surround os
Missing
Replace



20: Bonnet
Chipped
Multiple Chips



21: Screen Front
Chipped
UpTo 10mm



22: Roof
Scratched
Over 25mm Not Thru Paint



23: Wheel osr
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK