



VEHICLE INSPECTION REPORT

YF62RWU

Mini Countryman 1.6 Cooper S ALL4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/12/2012	Body Style	Hatchback	Last service miles	70,410
Year	2012	Keys	2	MOT Due	27/02/2027
Mileage	84,146 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	7	Doors	5
VIN	WMWZC52050WL66068	Last service date	13/02/2025		

£90 ADDITIONAL FEE

last service 13/2/25 @ 70,410 miles (7 services 4 main dealer) book EML light is on car has been plugged in and detects

Mixture control : fuel air mixture too lean

Oil pump pressure too high,

Engine oil pressure control valve line activation line disconnection

Tyres

NSF	MAZZINI	4.0mm
NSR	MAZZINI	5.0mm
OSF	MAZZINI	4.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Roof rails
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Sill ns
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Dented
With Paint Damage



9: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



12: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK