



VEHICLE INSPECTION REPORT

GV11UJT

Ford Focus 1.6 125 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/08/2011	Body Style	Hatchback	Last service miles	114,705
Year	2011	Keys	2	MOT Due	29/11/2026
Mileage	136,192 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WF0KXXGCBKBC47769	Last service date	22/05/2023		

last service 22/5/23 @ 114,705 miles (6 services 2 main dealer) book & print Exhaust blowing
 Nsr window does not open
 Parking sensors faulty

Tyres


NSF	SAILUN	5.0mm
NSR	SAILUN	5.0mm
OSF	SAILUN	5.0mm
OSR	MICHELIN	Damaged
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover of
Holed
Up To 3mm



2: Wheel of
Scratched
Over 50mm



3: Wing osf
Dented
Between 10mm + 30mm



4: Wing osf
Chipped
1 To 5



5: A Post os
Chipped
1 To 5



6: Door osf
Chipped
Edge Chip



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Door osr
Scratched
Over 25mm Not Thru Paint




9: Qtr Panel osr
Chipped
1 To 5



10: Wheel osr
Scratched
Up To 50mm



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Qtr Panel nsr
Dented
With Paint Damage



14: Wheel nsr
Scratched
Over 50mm



15: Door nsr
Scratched
Over 25mm Thru Paint



16: Door nsf
Chipped
Edge Chip



17: Door nsf
Scratched
Over 25mm Not Thru Paint



18: Door nsf
Chipped
1 To 5



19: Wing nsf
Dented
With Paint Damage



20: Wheel nsf
Scratched
Over 50mm



21: Bumper Front
Cracked
Over 25mm



22: Bonnet
Dented
Over 30mm



23: Screen Front
Chipped
UpTo 10mm



24: Other
N/A
N/A



25: Tyre osr
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK