



# VEHICLE INSPECTION REPORT

**LV70RGX**

## Mercedes-Benz A Class A180 AMG Line Executive 5dr Auto

nama  
GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	23/10/2020	Body Style	Hatchback	Last service miles	34,364
Year	2020	Keys	2	MOT Due	22/08/2026
Mileage	37,055 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	2	Doors	5
VIN	W1K1770842V069228	Last service date	19/08/2025		

£90 ADDITIONAL FEE

Last service 19/08/2025 at 34,364 miles- 2 services. Print

### Tyres

NSF	ZEETEX	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	ZEETEX	5.0mm
Spare		

### Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Partial leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

### Photos





## Condition Check



## Damage Photos



1: Door osr  
Scratched  
Over 25mm Not Thru Paint



2: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



3: Qtr Panel osr  
Scratched  
UpTo 25mm Not Thru Paint



4: Bumper Rear  
Poor Previous Repair  
Poor Paint



5: Qtr Panel nsr  
Scratched  
UpTo 25mm Not Thru Paint



6: Door nsr  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Bumper Front  
Scratched  
25 to 100mm Thru Paint



9: Bonnet  
 Scratched  
 Over 25mm Not Thru Paint

10: Roof  
 Dented  
 Between 10mm + 30mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK