



VEHICLE INSPECTION REPORT

GU58JPO

Honda Civic 1.8 i-VTEC SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	25/10/2008	Body Style	Hatchback	Last service miles	121,382
Year	2008	Keys	1	MOT Due	29/10/2026
Mileage	123,018 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	SHHFK27408U038182	Last service date	05/11/2025		

Last Service - 05.11.2025 at 121382 miles (4 services) Noise from front suspension when turning

Tyres

NSF	FALKEN	5.0mm
NSR	BUDGET	5.0mm
OSF	FALKEN	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Air conditioning
- Rear electric windows
- Drivers airbag
- Leather seat trim
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Central locking
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wing ofsf
Chipped
Multiple Chips



2: Wheel ofsf
Scratched
Over 50mm



3: Door osf
Dented
With Paint Damage



4: Door osr
Chipped
1 To 5



5: Door osr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Dented
With Paint Damage



9: Tailgate
Scratched
UpTo 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Door nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Door nsf
Scratched
Over 25mm Thru Paint



14: Wing nsf
Scratched
Over 25mm Not Thru Paint



15: Wheel nsf
Scratched
Over 50mm




16: Wing nsf
Chipped
1 To 5



17: Bumper Front
Scratched
Over 100mm Thru Paint



18: Bonnet
Chipped
Multiple Chips



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
1 To 5



21: Door Mirror Assy osf
Broken
Replace

22: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK