



VEHICLE INSPECTION REPORT

YP66XKL

Volkswagen Touran 1.6 TDI 115 S 5dr DSG

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	17/11/2016	Body Style	MPV	Last service miles	39,300
Year	2016	Keys	1	MOT Due	01/05/2026
Mileage	127,522 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	3		
VIN	WVGZZZ1TZH046388	Last service date	10/06/2020		

£90 ADDITIONAL FEE.

Last service 10/06/2020 at 39,300 miles- 3 main dealer services EML light on car has been plugged in and detects cylinder 3 flow plug circuit
 Service light on

Tyres

NSF	HANKOOK	5.0mm
NSR	LAUFENN	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel Trim nsf
Missing
Replace



4: Wing nsf
Chipped
Multiple Chips



5: Door nsf
Scratched
Over 25mm Thru Paint



6: B Post ns
Dented
Between 10mm + 30mm



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Lamp nsr
Broken
Replace



10: Tailgate
Dented
Over 30mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel osr
Dented
With Paint Damage



13: Door osr
Dented
With Paint Damage



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing osf
 Scratched
 UpTo 25mm Thru Paint



16: Wheel Trim osf
 Missing
 Replace



17: Screen Front
 Cracked
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK