



# VEHICLE INSPECTION REPORT

**YF62EXC**

## Peugeot Partner Tepee 1.6 HDi 115 Outdoor 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/11/2012	Body Style	MPV	Last service miles	71,125
Year	2012	Keys	2	MOT Due	27/07/2026
Mileage	73,263 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	5
Colour	BROWN	Number of stamps	11		
VIN	VF37J9HL0CJ687301	Last service date	04/08/2025		

£90 ADDITIONAL FEE.

Last Service - 04.08.2025 at 71125 miles (11 services)

### Tyres


NSF	BUDGET	5.0mm
NSR	TRIANGLE	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

### Features


- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Service indicator
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Radio/CD
- Full size spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Rusted



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



7: A Post ns  
Dented  
With Paint Damage



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel nsr  
Dented  
With Paint Damage




11: Wheel nsr  
Scratched  
Over 50mm



12: Tailgate  
Dented  
Between 10mm + 30mm



13: Roof  
Dented  
Between 10mm + 30mm



14: Qtr Panel osr  
Dented  
With Paint Damage



15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Scratched  
Over 25mm Thru Paint



17: Door osf  
Scratched  
Over 25mm Thru Paint



18: Door Mirror Assy nsf  
Broken  
Replace



19: Wheel osf  
Scratched  
Over 50mm



20: Wing osf  
Chipped  
1 To 5



21: Seat Back Cover nsr  
Scuffed  
Over 25mm

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK