



# VEHICLE INSPECTION REPORT

**LF17CNC**

## Land Rover Range Rover Evoque 2.0 Si4 HSE Dynamic 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	03/03/2017	Body Style	Estate	Last service miles	23,699
Year	2017	Keys	2	MOT Due	25/05/2026
Mileage	67,759 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	9
Colour	SILVER	Number of stamps	3		
VIN	SALVA2AG1HH225916	Last service date	07/09/2021		

Last Service - 07.09.2021 at 23699 miles (3 services) Intermittent engine rattle

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	PIRELLI	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	PIRELLI	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Door Moulding nsr  
Scuffed (Unpainted)  
Up To 100mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Tailgate  
Chipped  
1 To 5



10: Wheel osr  
Scratched  
Over 50mm




11: Door Moulding osr  
Scuffed (Unpainted)  
UpTo 100mm



12: Door osf  
Dented  
Over 30mm



13: Wheel osf  
Scratched  
Over 50mm



14: Screen Front  
Chipped  
UpTo 10mm



15: Qtr Panel osr  
 Scratched  
 Over 25mm Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK