



VEHICLE INSPECTION REPORT

MK66YBM

Honda HR-V 1.6 i-DTEC EX 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/09/2016	Body Style	Hatchback	Last service miles	130,496
Year	2016	Keys	2	MOT Due	18/10/2026
Mileage	147,070 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	8	Doors	5
VIN	3HGRU8790GM304369	Last service date	15/04/2025		

Last service 15/04/2025 at 130,496 miles- 8 services (6 main dealer) PGM-FI warning display

Tyres



NSF	DAVANTI	5.0mm
NSR	DAVANTI	5.0mm
OSF	DAVANTI	5.0mm
OSR	DAVANTI	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Electric sunroof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check




Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Fogdriving Lamp osf
Broken
Replace




4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Scratched
Over 25mm Thru Paint




6: Door nsf
Scratched
Over 25mm Thru Paint




7: Door nsr
Dented
Between 10mm + 30mm




8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Tailgate
Chipped
1 To 5




12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




13: Wheel osr
Scratched
Over 50mm




14: Door osr
Scratched
Over 25mm Thru Paint




15: Door osf
Scratched
Over 25mm Thru Paint




16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Over 50mm



18: Roof
Scratched
Over 25mm Thru Paint



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK