

VEHICLE INSPECTION REPORT

WP11JPJ

Ford Focus 1.6 125 Zetec 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/05/2011	Body Style	Hatchback	Last service miles	89,086
Year	2011	Keys	1	MOT Due	24/03/2027
Mileage	101,486 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	10	Doors	5
VIN	WF0KXXGCBKBL01084	Last service date	25/03/2025		

Last Service - 25.03.2025 at 89086 miles (10 services) Gear selector has lots of play when in gear
 Exhaust blowing


Tyres

NSF	SAILUN	3.0mm
NSR	FIRESTONE	3.0mm
OSF	SAILUN	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Front armrest
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wheel of
Scratched
Up To 50mm



3: Wing osf
Scratched
Over 25mm Not Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osf
Scratched
Over 25mm Not Thru Paint



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Rear TowEye Cvr
Missing
Replace



10: Qtr Panel nsr
Chipped
1 To 5



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Door nsr
Chipped
1 To 5



13: Door nsr
Scratched
Over 25mm Not Thru Paint



14: Door nsf
Chipped
Edge Chip



15: Door nsf
Chipped
1 To 5



16: Wing nsf
Chipped
1 To 5




17: Wing nsf
Scratched
Over 25mm Not Thru Paint



18: Bumper Front
Chipped
Multiple Chips



19: Bonnet
Chipped
1 To 5



20: Screen Front
Chipped
UpTo 10mm




21: Door osr
Chipped
1 To 5



22: Door osr
Dented
Between 10mm + 30mm



23: Door nsr
Dented
Over 2 UpTo 10mm



24: Roof
Chipped
1 To 5



25: Other
N/A
N/A



26: Roof
Scratched
Over 25mm Not Thru Paint



27: Carpets Front
Holed
Over 3mm



28: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK