



VEHICLE INSPECTION REPORT

GF65JJX

Peugeot 308 1.6 BlueHDi 120 Active 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	27/10/2015	Body Style	Estate	Last service miles	15,278
Year	2015	Keys	1	MOT Due	29/09/2026
Mileage	58,264 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	3		
VIN	VF3LCBZHFS211863	Last service date	13/09/2016		

Clutch replaced 01/06/2025.

Last service 13/09/2016 at 15278 miles (3 main dealer services). Brake Judder

Tyres


NSF	HANKOOK	Damaged
NSR	BRIDGESTONE	5.0mm
OSF	HANKOOK	3.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm




4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Screen Front
Cracked
Replace



6: Door nsf
Scratched
Up To 25mm Thru Paint



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Wheel osr
Scratched
Over 50mm



12: Tyre nsf
Damaged
Replace



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK