



# VEHICLE INSPECTION REPORT

**A8KPU**

## Mercedes-Benz GLE GLE 250d 4Matic Sport 5dr 9G-Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	09/09/2015	Body Style	Estate	Last service miles	93,082
Year	2015	Keys	2	MOT Due	08/09/2026
Mileage	93,779 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	9
Colour	BLACK	Number of stamps	10		
VIN	WDC1660042A627452	Last service date	11/03/2026		

£100 ADDITIONAL FEE.

Last service 11/03/2026 at 93,082 miles- 10 services.

### Tyres


NSF	CONTINENTAL	Damaged
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

## Photos






# Condition Check




## Damage Photos




1: Bonnet  
Chipped  
Multiple Chips




2: Bumper Front  
Scratched  
Over 100mm Thru Paint




3: Wheel nsf  
Scratched  
Over 50mm




4: Wing nsf  
Scratched  
Over 25mm Thru Paint




5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint




6: Door nsf  
Chipped  
1 To 5




7: Door nsr  
Scratched  
Over 25mm Thru Paint




8: Tyre nsf  
Damaged  
Replace




9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm




10: Wheel nsr  
Scratched  
Over 50mm




11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




12: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm




13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint




14: Wheel osr  
Scratched  
Over 50mm




15: Door osr  
Poor Previous Repair  
Poor Paint



16: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**            Average  
**Seat Condition**            Average

**Upholstery Condition**    Average  
**Odour**                        No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

**Additional fees may apply to some vendors.**  
**Please note buyers rate increase from 01/01/2025**

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK