



VEHICLE INSPECTION REPORT

AY14RXU

Kia Sportage 2.0 CRDi KX-4 5dr Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	08/04/2014	Body Style	Estate	Last service miles	91,421
Year	2014	Keys	2	MOT Due	27/09/2026
Mileage	101,077 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	1		
VIN	U5YPC813SEL443627	Last service date	06/09/2024		

£100 ADDITIONAL FEE

last service 6/9/24 @ 91,421 miles (1 service) print Sunroof gets stuck
 Only drivers window works

Tyres

NSF	WANLI	6.0mm
NSR	TRIANGLE	3.0mm
OSF	WANLI	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
UpTo 3mm



2: Wheel of
Corroded
Light



3: Wing osf
Chipped
1 To 5



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osr
Chipped
1 To 5



6: Door osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Corroded
Light



8: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



9: Tailgate
Scratched
Over 25mm Not Thru Paint



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Wheel nsr
Corroded
Light



12: Qtr Panel nsr
Dented
2 Or Less Up To 10mm



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Door nsr
Scratched
Over 25mm Not Thru Paint



15: Door nsf
Chipped
1 To 5



16: Door nsf
Scratched
Over 25mm Not Thru Paint



17: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



18: Wing nsf
Scratched
Over 25mm Thru Paint



19: Wheel nsf
Corroded
Light



20: Bumper Front
Scratched
Over 100mm Thru Paint



21: Bonnet
Chipped
1 To 5



22: Screen Front
Chipped
UpTo 10mm



23: Door osr
Dented
2 Or Less UpTo 10mm



24: Door nsf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	Fault	Steering	OK
Sat nav	OK		