



VEHICLE INSPECTION REPORT

GY20RHU

Volkswagen Polo 1.0 TSI 95 Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	15/07/2020	Body Style	Hatchback	Last service miles	51,994
Year	2020	Keys	2	MOT Due	24/06/2026
Mileage	64,304 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	4	Doors	5
VIN	WVVZZZAWZLU075127	Last service date	27/08/2024		

£90 ADDITIONAL FEE

Last service 27/08/2024 at 51,994 miles- 4 main dealer services. Print Driver door need adjusting as catching on the wing when opening wing damage out of line

Tyres


NSF	RAPID	5.0mm
NSR	AVON	5.0mm
OSF	LAUFENN	5.0mm
OSR	AVON	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Front headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos







Condition Check




Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5




5: Door nsf
Scratched
Over 25mm Thru Paint




6: Door nsr
Dented
With Paint Damage




7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




8: Bumper Rear
Scratched
25 to 100mm Thru Paint




9: Tailgate
Scratched
UpTo 25mm Thru Paint




10: Qtr Panel osr
Scratched
Over 25mm Thru Paint




11: Door osr
Dented
Between 10mm + 30mm




12: Door osf
Dented
Over 30mm



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Dented
Over 30mm



15: Bumper Front
Insecure
Action Required

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK