



VEHICLE INSPECTION REPORT

YC12WGO

BMW 6 Series 640d SE 2dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	09/05/2012	VIN	WBALX720X0DX65527	Last service date	01/10/2018
Year	2012	Body Style	Coupe	Last service miles	41,841
Mileage	78,107 Miles Warranted	Keys	1	MOT Due	07/01/2027
Fuel Type	Diesel	Service history	Yes	Gearbox	AUTOMATIC
Colour	BLUE	Number of stamps	1	Gears	8

Last service 01/10/2018 at 41,841 miles- 1 service confirmed by Group 1 MINI, Hailsham

Tyres

NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Service indicator
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front armrest
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Dented
UpTo 30mm (Alloy)



5: Door nsf
Chipped
Edge Chip



6: Qtr Panel nsr
Dented
Over 30mm



7: Wheel nsr
Dented
UpTo 30mm (Alloy)



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Boot Lid
Scratched
Over 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
Over 30mm



12: Door osf
Scratched
Over 25mm Thru Paint




13: Roof
Chipped
1 To 5



14: Wing osf
Scratched
Over 25mm Thru Paint



15: A Post os
 Scratched
 Over 25mm Thru Paint



16: Screen Front
 Chipped
 Over 10mm



17: Wheel osf
 Scratched
 Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK