



VEHICLE INSPECTION REPORT

LB21WMZ

Toyota C-Hr 1.8 Hybrid Design 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	25/06/2021	Body Style	Hatchback	Last service miles	21,850
Year	2021	Keys	2	MOT Due	24/06/2026
Mileage	23,290 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	4	Doors	5
VIN	NMTK33BX40R091300	Last service date	30/05/2025		

£100 ADDITIONAL FEE.

Last service 30/05/2025 at 21850 miles (4 services (1 main dealer)).

Tyres


NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Blind spot information
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Door nsr
Scratched
Over 25mm Thru Paint



4: Wheel nsr
Scratched
Over 50mm



5: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



8: Door osr
Chipped
1 To 5



9: Door osf
Chipped
Edge Chip



10: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK