



VEHICLE INSPECTION REPORT

RA21LMJ

Honda CR-V 2.0 i-MMD Hybrid EX 5dr eCVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	13/07/2021	Keys	2	CAP Clean	£15,050.00
Year	2021	Service history	Yes	CAP Average	£13,700.00
Mileage	110,894 Miles Warranted	Service documents	Printout	CAP Below	£12,350.00
Fuel Type	Hybrid Electric	Number of stamps	7	Gearbox	CVT
Colour	BLACK	Last service date	25/02/2025	Gears	1
VIN	JHMRT6880MX204306	Last service miles	105,970		
Body Style	Estate	MOT Due	12/07/2025		

Last Service - 25.02.2025 at 105970 miles (7 main dealer services)

Tyres

NSF	BUDGET	4.0mm
NSR	HANKOOK	3.0mm
OSF	BUDGET	5.0mm
OSR	HANKOOK	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Telephone
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
Over 30mm



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Dented
With Paint Damage




10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Wheel osr
Scratched
Up To 50mm



13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		