



# VEHICLE INSPECTION REPORT

**T66ATW**

## BMW 3 Series 320d SE 5dr Step Auto

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	03/03/2021	Body Style	Estate	Last service miles	78,126
Year	2021	Keys	2	MOT Due	05/07/2026
Mileage	84,561 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	BLACK	Number of stamps	9		
VIN	WBA6L52070FJ38303	Last service date	31/01/2026		

last service 31/1/26 @ 78,126 miles (9 services 5 main dealer)  
 both engine mounts replaced on 31/3/26 @ 84,446 miles Service due message displayed

### Tyres


NSF	YOKOHAMA	5.0mm
NSR	KUMHO	5.0mm
OSF	YOKOHAMA	5.0mm
OSR	KUMHO	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos




1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Up To 50mm



4: Door nsr  
Dented  
Between 10mm + 30mm



5: Qtr Panel nsr  
Dented  
Over 30mm



6: Door nsf  
Dented  
Between 10mm + 30mm



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Qtr Panel osr  
Chipped  
1 To 5



9: Door osr  
 Poor Previous Repair  
 Rippled UpTo 30%

10: Wheel osf  
 Scratched  
 Up To 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK